

**PROPOSED WORKS FOR TREATMENT OF EROSION AND REHABILITATION OF BEACHES
AT LE PRINCE MAURICE HÔTEL**

ENVIRONMENTAL IMPACT ASSESSMENT REPORT

CONTENTS

Section	Description	Page
0	EXECUTIVE SUMMARY.....	0-1
1	INTRODUCTION.....	1-1
1.1	The Promoter.....	1-1
1.2	Description of Proposed Works	1-1
1.3	The Project Team.....	1-1
1.4	Project Timeframe.....	1-2
1.5	Scope and Methodology of the Environmental Impact Assessment	1-2
2	ENVIRONMENTAL FRAMEWORK IN MAURITIUS.....	2-1
2.1	The Environmental Protection Act 2002.....	2-1
2.2	Other Main Applicable Legislations and Policies	2-1
2.2.1	The National Development Strategy 2003 & Planning Policy Guidance 2004	2-1
2.2.2	The Fisheries and Marine Resources Act 2007	2-1
2.2.3	The National Biodiversity Strategic and Action Plan (2006-2015).....	2-2
2.2.4	The Moka Flacq Outline Scheme	2-2
2.3	International Treaties and Agreements	2-2
3	BASELINE ENVIRONMENT.....	3-1
3.1	Project Location.....	3-1
3.2	Geomorphology and Sedimentology.....	3-1
3.2.1	General Context	3-2
3.2.2	The Shoreline.....	3-2
3.2.3	The Reef Flat.....	3-3
3.2.4	The Sediment Transit along the Shoreline.....	3-4
3.2.5	The Coral Sand Characteristics.....	3-5
3.3	Bathymetrical Context	3-5
3.4	Oceanographical Context.....	3-6
3.4.1	Currents	3-6
3.4.2	Lagoonar Swells and Waves	3-6

3.5	Marine Environment.....	3-7
3.5.1	The Bathing Area (Northern Deep Reef Flat) (A)	3-8
3.5.2	The Northern shallow reef flat (B)	3-8
3.5.3	The Eastern reef flat	3-10
3.5.4	Ecological sensitivity	3-11
3.6	Erosion Phenomena Analysis on the Northern Main Beach	3-11
3.7	Monitoring of the Erosion Problems along the Hotel's Coastline one Year after the Initial Study.	3-12
4	PROJECT DESCRIPTION	4-1
4.1	Initial Scope of Works.....	4-1
4.2	Erosion Treatment of the East End of the Beach at the Rocky Headland Level – Main North Beach	4-1
4.3	Erosion Treatment of the East Part – Main North Beach.....	4-2
4.4	Erosion Treatment after the Filaos Area – Main North Beach.....	4-4
4.5	Erosion Treatment of the Exposed Small Beach in the East	4-5
4.6	Erosion Treatment of the south-east beach.....	4-6
4.7	Natural Material Requirements	4-7
4.8	The Casuarina Trees Issue.....	4-8
4.9	Final Scope of Works.....	4-8
5	PREDICTED ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES DURING BEACH REHABILITATION WORKS.....	5-1
5.1	Impact Identification and Scoping	5-1
5.1.1	Introduction.....	5-1
5.1.2	Risk Assessment Matrix.....	5-1
5.1.3	Predicted Impacts without Mitigation Measures.....	5-1
5.2	Water Quality (Total Suspended Solids).....	5-2
5.3	Beach Stress	5-3
5.4	Beach Access	5-4
5.5	Local Air Quality	5-4
5.6	Noise	5-4
5.7	Spillage of Fuel	5-5
5.8	Training, Health & Safety measures.....	5-5
5.9	Summary Table of Impacts with Mitigation Measures.....	5-5
6	ENVIRONMENTAL MONITORING PLAN	6-1

6.1	EMP during Rehabilitation Works	6-1
6.2	EMP after Completion of Works.....	6-1
7	CONCLUSION.....	7-1
8	REFERENCES.....	8-1

LIST OF APPENDICES

Appendix A	Administrative Documents
Appendix B	The Main North Beach: Past and Present State
Appendix C	The Sediments analysis reports
Appendix D	The Compared Beach Profiles 2009 & 2010
Appendix E	The Rocky Headland: Present and Future State
Appendix F	Methodology Statement for Sand Cleansing and Recovery

LIST OF DRAWINGS

Drawing No. DPM11/EIA/01	: Reef Flat - Geomorphological and Biological Units Encountered
Drawing No. DPM11/EIA/02	: Bathymetric Map
Drawing No. DPM11/EIA/03	: Global Hydrodynamics Mechanism and Patterns
Drawing No. DPM11/EIA/04(A&B)	: Means Sea Levels & Location of Pipes
Drawing No. DPM11/EIA/05(A&B)	: Location, Type and Extent of Beach Rehabilitation Works

LIST OF TABLES

Table 1: Summary Table of Impacts after Implementing Mitigation Measures.....	0-2
Table 2: Project Key Milestones	1-2
Table 3: Size Characteristics of Sediment Samples	3-5
Table 4: Summary Table of Impacts with Mitigation Measures	5-2
Table 5: Summary of residual impacts if any after mitigation measures.....	5-6

LIST OF FIGURES

Figure 1: Aerial view of the site – location map	3-1
Figure 2: Beach Profiles 32, 33 & 34 showing appearance of the upper beach slope and the present erosive step.....	4-3
Figure 3: Risk Assessment Matrix	5-1
Figure 4: Proposed Positioning Of Geo-Textile Screens.....	5-3

LIST OF PICTURES

Picture 1 & Picture 2: The western part of the beach, subject to a natural sand accretion ...	3-2
Picture 3: Appearance of the central part of the beach, in equilibrium.....	3-3
Picture 4, Picture 5 & Picture 6: sectors having erosion on the east side.....	3-3
Picture 7 & Picture 8: Seagrass covers much of the shallow reef flat.....	3-4
Picture 9: The 3 different biotopes investigated on site.....	3-7

Picture 10 & Picture 11: The silty sea-beds in the middle of bathing area.....	3-8
Picture 12 & Picture 13: The Middle Dense Seagrass Meadows of Halodule Wrightii.....	3-9
Picture 14 & Picture 15: Cyanobacteria Development on Seagrass and Algae Turf on Seagrass Leaves.....	3-9
Picture 16 & Picture 17: Rocks entirely covered with the brown algae Padina	3-10
Picture 18 &Picture 19: The cowries Cypraea annulus and the Synapta maculata.....	3-10
Picture 20 &Picture 21: Closeup of the area to be treated.....	4-2
Picture 22: Rocky Threshold to be raised	4-2
Picture 23 &Picture 24: East Part of the Main Beach	4-3
Picture 25: In red on the photo, the required beach profile	4-5
Picture 26 & Picture 27: Recharging the beach with sand to give it a convex profile (it is now concave), providing better stability against heavy swells.	4-6
Picture 28: Recharging the beach with sand and follow a gentle slope towards the sea.....	4-6