

**Coastal Improvement Works at Ambre Resorts & Spa Mauritius
SUN Resort**

Table of Contents

Executive Summary	3-5
Chapter 1: Overview	6-7
1.1 Project location	
1.2 Present Status of the Hotel	
1.3 The Study and the Report	
1.4 The Proposals	
1.5 Execution of the EIA	
1.6 Time Frame	
Chapter 2: Climatic Conditions & Coastal Environment of the Project Area	8-15
2.1 General Climatic Conditions	
2.2 Temperature	
2.3 Rainfall	
2.4 Regional Geomorphology	
2.5 The Physical & Coastal Environment	
2.6 Tide and Water Levels	
2.7 General Current Pattern	
2.8 Coastal Mapping, Beach Topography and Bathymetry	
2.9 Beach Vulnerability Map	
2.10 Lagoon Substrate Classification	
2.11 Qualitative Observation of Lagoon Water	
Chapter 3: Project Description	16-19
3.1 Proposed Project Components	
3.2 Proposed Project Locations	
3.3 Project Justification	
3.4 Details of Proposals & Methods	
3.4.1 Zone 1	
3.4.1.a Method	
3.4.2 Zone 2, 3 & 4	
3.4.2.a Method	
3.4.3 Landscaping of the coast-beach interphase	
3.5 Proposal for a Sports Jetty	
3.6 Proposed EIA Process and Works Schedule	
Chapter 4: Impact and Impact Mitigating Measures	20-22
4.1 Present Impact	
4.2 Impact of Proposed Project Components	
4.2.1 Impact from resolving coastal erosion issues	
4.2.2 Impact from building of a Sports Jetty	
4.3 Impact Mitigating Measures	

Coastal Improvement Works at Ambre Resorts & Spa Mauritius SUN Resort

Chapter 5: Environment Monitoring Plan **23-24**

- 5.1 Activities at Implementation Stage
 - 5.1.1 Zoning and preparation of Site
 - 5.1.2 Materials
 - 5.1.3 Machinery and Stocking of Fuel
 - 5.1.4 Waste Management
 - 5.1.5 Management of Site for implementation purpose
 - 5.1.6 Log book and Reports

Chapter 6: Conclusion **25**

Figures

- Figure 1 Location Plan & Site Plan
- Figure 2 Coastal Mapping
- Figure 3 Topography & nearshore bathymetry
- Figure 4 2D & 3D representation of nearshore topography and bathymetry
- Figure 5 Beach Profile Location
- Figure 5a Existing profiles 1-4
- Figure 5b Existing profiles 5-6
- Figure 5c Existing profiles 7-8
- Figure 5d Existing profiles 9-10
- Figure 5e Existing profiles 11-12
- Figure 5f Existing profiles 13-14
- Figure 5g Existing profiles 15-17
- Figure 5h Existing profiles 18-19
- Figure 5i Existing profiles 20-21
- Figure 6 Beach Vulnerability
- Figure 7 Beach Size Classifications
- Figure 8 Image Classifications for Lagoon Substrate
- Figure 9 Coastal Circulation in the study area
- Figure 10 Proposed Profiles
- Figure 11 Proposed coastal improvement Plan
- Figure 12 Section of Profile Jetty & Elevation

Plates

Annexes

- Annex 1 Industrial lease with Ministry of Housing & Lands
- Annex 2 Subletting Agreements between Ministry of Housing & Lands and Armand Apavou & Co Ltd
- Annex 3 License Agreements between Armand Apavou & Co Ltd & Sun Resorts Ltd
- Annex 4 Results of Digital Shoreline Analysis System