

ENVIRONMENT
IMPACT
ASSESSMENT



Proposed Cancer Hospital at Coromandel
by
Coromandel Hospital Co. Ltd

December 2019

**MINISTRY OF ENVIRONMENT, SOLID WASTE MANAGEMENT
& CLIMATE CHANGE**

DEPARTMENT OF ENVIRONMENT

Proponent: Coromandel Hospital Co Ltd
Rep. by Mrs Bibi Shaeen Banu
JOOMAYE (born JAULIM)

Signature: 11th Floor, Bramer House
Cybercity, Ebene

Contact Persons: (i) Dr Ashish Sharma
Tel: 697 5768/5 971 683
(ii) Dr Zouberr Joomaye
Tel: 696 1320/ 5 2597 490

Land Surveyor: Kritanun Seebaruth
Tel: 5 250 2972

Local Architect: Vanina Naidoo
Tel: 5 704 5019/ 5 987 1614

Soil Scientist: GeoCrust Ltd
Consulting Geotechnical Engineers
& Geoscientists
Tel: 5 290 1350

Structural Engineer: A.S.Gopee
Tel: 464 4266

Quantity Surveyor: Ong Seng Goburdhun Partners Ltd
Tel: 454 4854/55/ 5 256 1719

EIA Report Editor: Dr (Mrs) Marie Cecile Alixe Bellouard Elliott
PhD Town and Country Planning, Montpellier
DESS (Diplome d'Etudes Superieures
Specialisees), Ecologie et Amenagement
Planning and Environment Consultant

Signature: (M.C.A.B.Elliott)
Tel No. 5 772 9457

Table of Contents

1.0	PROPOSED PRIVATE CANCER HOSPITAL AT COROMANDEL	1
1.1	Non-technical summary	1
2.0	INTRODUCTION AND LEGAL FRAMEWORK	5
2.1	Introduction	5
2.2	The Environment Protection Act 2002, as amended	6
3.0	SITE AND PROJECT DESCRIPTION	8
3.1	Site description	8
3.1.1	Site ownership	8
3.1.2	Present zoning of site	8
3.1.3	Plans and policies	8
3.1.4	Site characteristics	9
3.1.4.1	Site location	9
3.1.4.2	Landform	9
3.1.4.3	Land use on subject site	10
3.1.4.4	Flora and fauna/Sensitive features	10
3.1.4.5	The surrounding environment	10
3.1.4.6	Other attributes of the area	10
3.1.4.8	Other similar projects in the surroundings	10
3.1.4.9	Availability of infrastructure and public utilities	11
3.2	Project description	11
3.2.1	Project initiator	11
3.2.2	Particulars of the project	11
3.2.2.1	Overall design and layout	11
3.2.2.2	The Basement Floor	12
3.2.2.3	The Ground Floor	12
3.2.2.4	The First Floor	12
3.2.2.5	The Second Floor	12
3.2.2.6	The Third Floor	13
3.2.2.7	The Fourth Floor	13
3.2.2.8	Architectural plans and associated features	13
3.2.2.9	Setbacks	14
3.3	Fencing	14
3.4	Access	14
3.5	Vehicular traffic and parking issues	15
3.6	Security of the patients, staff and visitors	15
3.7	Need and justification of the undertaking	15
3.8	Schedule of implementation	16

4.0	METHOD OF ASSESSMENT	17
4.1	Baseline data	17
4.1.1	Data collection methodology	17
4.1.2	Geotechnical report	18
4.1.3	Land survey report	18
4.1.4	Consultations	18
5.0	IDENTIFICATION OF MAJOR ENVIRONMENTAL IMPACTS	19
5.1	Impact identification	19
5.2	Construction phase: Environmental impacts	19
5.2.1	Site clearing/preparation and storage of materials	19
5.3	Operational phase: Environmental impacts	19
5.3.1	General comments	19
5.3.2	Handling and management of solid waste	20
5.3.3	Collection and disposal of liquid effluents	21
5.3.4	Supply of utility services (water and electricity)	21
5.3.5	Noise and air pollution	22
5.3.6	Health and safety hazards	22
5.3.7	Vehicular traffic implications of the undertaking	23
5.3.8	Socio-economic effects of the hospital development	23
6.0	ENVIRONMENTAL IMPACTS: PROPOSED MITIGATING MEASURES	24
6.1	Overview	24
6.2	Construction phase: Proposed mitigating measures	24
6.2.1	Site clearing and preparation	24
6.2.2	Abatement of noise and air pollution	25
6.2.3	Vehicular traffic management	25
6.3	Operational phase: Proposed mitigating measures	25
6.3.1	Collection and management of ordinary and hazardous solid waste	25
6.3.2	Collection and disposal of liquid effluents	26
6.3.3	Collection and evacuation of rain-water	27
6.3.4	Supply of utility services (water and electricity)	27
6.3.5	Health and fire/safety hazards	28
6.3.6	Traffic implications of the undertaking	29
6.3.7	Socio-economic impacts of the undertaking	30
7.0	ENVIRONMENTAL MONITORING PLAN	32
7.1	MONITORING AND AUDITING	32
7.1.1	Overview	32
7.2	Operational phase	32

7.3 Environmental Monitoring Unit.....	32
7.4 Construction	33
7.4.1 Site clearing and preparation.....	33
7.5 Environmental Monitoring Plan	33
7.6 Maintenance	34
7.7 Auditing	34
7.8 Control by statutory authorities	35
7.9 Particulars of the Environmental Monitoring Plan.....	35
8.0 ALTERNATIVES AND CONCLUSIONS.....	38
8.1 Outline of alternatives to the project.....	38
8.2 Conclusions	40

Annexes

<u>Annex 1 (Letter from ‘Polyclinique De L’Ouest Ltee’)</u>
<u>Annex 1A (Profile of Polyclinique De L’Ouest Ltee’)</u>
<u>Annex 2 (CV OF Dr Ashish Sharma)</u>
<u>Annex 3 (Lease Agreement with Development Bank of Mauritius Ltd)</u>
<u>Annex 4 (Clearance from Development Bank of Mauritius Ltd)</u>
<u>Annex 5 (Outline Planning Permission)</u>
<u>Annex 6 (Location Plan)</u>
<u>Annex 7 (Land Form - Contour Plan)</u>
<u>Annex 8 (Context Plan)</u>
<u>Annex 9 (Certificate of Incorporation - Coromandel Hospital Co Ltd)</u>
<u>Annex 10 (Basement Floor)</u>
<u>Annex 11 (Ground Floor)</u>
<u>Annex 12 (First Floor)</u>
<u>Annex 13 (Second Floor)</u>
<u>Annex 14 (Third Floor)</u>
<u>Annex 15 (Fourth Floor)</u>
<u>Annex 16 (Elevations 1 and 2)</u>
<u>Annex 16A (Elevations 3 and 4 and Sections)</u>
<u>Annex 17 (Artistic Impression)</u>
<u>Annex 17A (Artistic Impression)</u>
<u>Annex 18 (Setbacks)</u>
<u>Annex 19 (Geotechnical Report)</u>
<u>Annex 20 (Clearance from Ministry of Health)</u>
<u>Annex 20A (Major features and specifications of the incinerator)</u>
<u>Annex 21 (Clearance from the Central Electricity Board)</u>