

**PROPOSED WORKS FOR TREATMENT OF EROSION AND REHABILITATION OF BEACHES
AT THE TROPICAL ATTITUDE HOTEL**

ENVIRONMENTAL IMPACT ASSESSMENT REPORT

CONTENTS

0 EXECUTIVE SUMMARY	0-1
1 INTRODUCTION.....	1-1
1.1 The Promoter	1-1
1.2 Description of Proposed Works.....	1-1
1.3 The Project Team.....	1-2
1.4 Project Timeframe.....	1-3
1.5 Scope and Methodology of the Environmental Impact Assessment	1-3
1.6 Public Consultations	1-3
2 ENVIRONMENTAL FRAMEWORK IN MAURITIUS	2-1
2.1 The Environment Protection Act 2002	2-1
2.2 Other Main Applicable Legislations and Policies.....	2-1
2.2.1 The National Development Strategy 2003 & Planning Policy Guidance 2004.....	2-1
2.2.2 The Fisheries and Marine Resources Act 2007.....	2-1
2.2.3 The National Biodiversity Strategic and Action Plan (2006-2015).....	2-2
2.2.4 The Moka Flacq Outline Scheme.....	2-2
2.3 International Treaties and Agreements.....	2-2
3 BASELINE ENVIRONMENT	3-1
3.1 Project Location.....	3-1
3.2 The Marine Environment.....	3-2
3.2.1 Methodology of Survey.....	3-2
3.2.2 Description of the Geomorphological and Biological Units	3-3
3.2.3 Ecological value and sensitivity of the study zone.....	3-12
3.2.4 Inventories of observed species on the site	3-17
3.2.5 Hydrodynamics and Currents	3-19
3.2.6 Lagoon use.....	3-21
4 PROJECT DESCRIPTION	4-1
4.1 Scope of Works	4-1
4.2 Recharge of the Beach.....	4-1
4.3 Construction of Breakwaters	4-5
4.4 Construction of Groin.....	4-5
4.5 Requirements.....	4-6
5 PREDICTED ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES DURING THE BEACH REHABILITATION WORKS.....	5-1

5.1	Impact Identification and Scoping.....	5-1
5.1.1	Introduction.....	5-1
5.1.2	Risk Assessment Matrix	5-1
5.1.3	Predicted Impacts without Mitigation Measures	5-2
5.2	Marine Biodiversity.....	5-3
5.3	Water Quality (Total Suspended Solids).....	5-4
5.4	Beach Stress.....	5-4
5.5	Beach Access	5-5
5.6	Local Air Quality	5-5
5.7	Noise	5-5
5.8	Spillage of Fuel.....	5-6
5.9	Training, Health & Safety measures.....	5-6
5.10	Summary Table of Impacts with Mitigation Measures	5-6
6	ENVIRONMENTAL MONITORING PLAN	6-1
6.1	EMP during Rehabilitation Works	6-1
6.2	EMP after Completion of Works.....	6-2
7	CONCLUSION	7-1
8	REFERENCES	8-1

LIST OF APPENDICES

Appendix A Administrative Documents

LIST OF DRAWINGS

Geomorphological and Biological Map
Maps of Corals and Stocks Vitality
Sensitivity Map
Map of Current – Receding Tide
Map of Current – Rising Tide
Beach Rehabilitation Works
Beach Profiles
Old & New Levels (HWM, LWM, MSL)
Breakwater on Geomorphological and Biological Map

LIST OF TABLES

Table 1: Summary Table of Impacts after Implementing Mitigation Measures	0-2
Table 2: Project Key Milestones	1-3
Table 3: Inventories of observed species on the site	3-19
Table 4: Calculation of Volumes for Beach Recharge.....	4-4
Table 5: Risk Assessment Matrix	5-1
Table 6: Summary Table of Impacts with Mitigation Measures	5-2
Table 7: Summary of residual impacts if any after mitigation measures.....	5-7
Table 8: Inspection and Monitoring Programme (Construction Phase).....	6-1

LIST OF FIGURES

Figure 1: Aerial view of the site – Location map	3-1
Figure 2: Trou d'Eau Douce Bay and Reef	3-2
Figure 3: Map of the transects and explored stations.....	3-3
Figure 4: Geomorphological and Biological Map.....	3-4
Figure 5: Map of Corals and Stocks Vitality	3-13
Figure 6: Limits of Algae Proliferation in 2005, 2009 and 2011.....	3-15
Figure 7: Sensitivity Map.....	3-16
Figure 8: Current Monitoring - Receding Tide.....	3-20
Figure 9: Current Monitoring - Rising Tide	3-20
Figure 10: Projected Beach for Beach Recharge (in context)	4-2
Figure 11: Projected Beach for Beach Recharge (drawing).....	4-2
Figure 12: Profiles for Beach Recharge	4-4
Figure 13: Typical Cross-section of Breakwaters	4-5
Figure 14: Location of Breakwaters shown in the Geomorphological and Biological Context.....	5-3