

Table of Content

Executive Summary	3
Table of Content.....	4
Chapter 1 Overview	6
1.1. Preamble.....	6
1.2. Purpose of the report	6
1.2.1. Introduction.....	6
1.2.2. Site Location	7
Chapter 2 The Physical Environment at the site	8
2.1. Climatological Factors	8
2.1.1. Rainfall.....	9
2.1.2. Sea-surface temperature.....	9
2.1.3. Atmospheric pressure.....	10
2.1.4. Waves.....	10
2.1.5. Storm Surge.....	12
2.1.6. Nearshore wave transformation	12
2.1.7. Longshore current	12
2.1.8. Tides and Sea Levels.....	13
2.1.9. Tides at the site	14
2.2. Tropical Climatology	15
2.2.1 Historical Events	15
2.2.2. Tropical Cyclone Frequency	17
Chapter 3 Survey Methods and Observations	19
3.1. Survey Methods	19
3.2 General Observations	20
3.2.1 Sediment.....	20
3.2.2 Beach topography & bathymetry	20
3.2.3 Appearance of water	23
3.3. Observations made along transect lines	23
3.4. Beach Profile.....	31
3.5. Waves and Currents	32
Chapter 4 Proposal for rearrangement of loose rocks and creation of a sun bathing area.....	34
4.1. Proposal for relocation and rearrangement of the loose rocks.....	34
4.1.1. Technical details	37
4.1.2. Maintenance	38
4.1.3. Reef enhancement	38
Chapter 5 Impacts and mitigation measures.....	39
5.1. Impacts	39
5.2. Mitigation.....	40
5.3. Environment monitoring plan	43
Chapter 6 Alternatives.....	45
6.1.1. The ‘Do Nothing’ Option.....	45
6.1.2. Removal of loose rocks.....	45
6.1.3. Creation of beach over the loose rocks	45
6.1.4. Manual clearing of the harmful organism.....	45
6.1.5. Marking off the area.....	46
Conclusion.....	47
References.....	48

Annex 1

Industrial Site Lease for SPA on the SHORES Ltd - Shanti Maurice – A Nira Resort
Building and Land Use Permits

Annex 2

Species List

Annex 3

Layout plan for Shanti Maurice with beach profile lines
Beach profile in front of Shanti Maurice

Annex 4

Proposed location for revetment and semi submerged beach